


LEFT ENGINE



CONTINENTAL

A E R O S P A C E T E C H N O L O G I E S

**ENGINE
LOG
BOOK**

Service Information

Consult the Continental web site at <http://www.continental.aero> for engine related news or announcements. The web site contains useful information for Continental engine owners, including service information and illustrated parts catalogs.

If Internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or 1-251-436-8299 for International customers

Warranty Information

This product is covered by Continental Aerospace Technologies™ product warranty. To read or download a copy for your records, please visit the Product Warranty page on our web site at: <http://www.continental.aero/services/warranty.aspx> or scan the QR Code to the right to navigate to the page:



Instructions for Continued Airworthiness

For complete access to the engine Instructions for Continued Airworthiness, Illustrated Parts Catalogs, Service Documents, Technical Briefs, company news, and upcoming events, please take a few moments to register the serial number of your engine on our web site: <http://www.continental.aero/services/owner-registration.aspx> or scan the QR Code to the right to navigate to the page:



Engine Returns

Return engines for core credit with this log book to:
Continental Aerospace Technologies
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:
Continental Services
Factory Service Center
8600 County Road 32
Fairhope, Alabama 36532 USA

**USE ONLY FUEL SPECIFIED IN OPERATOR'S
MANUAL OR TYPE CERTIFICATE DATA SHEET
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



PRODUCTION CERTIFICATE NO. 508

Printed: 10.28.2024

Test Date: 10.26.2024

Engine model R-TSI0360EB1B , serial number 1048107
was rebuilt by Continental Aerospace Technologies, Inc. in accordance with
approved design data and the applicable requirements of 14 CFR, Parts 21 and
43 of the Federal Aviation Regulation. The approved design data for this
engine incorporates all changes required by applicable FAA Airworthiness
Directives and Continental Service Bulletins.

CONTINENTAL AEROSPACE TECHNOLOGIES,
INC.

Aircraft Engine Test Verification

This document verifies that the engine model listed below has satisfactorily completed all testing listed below in accordance with GM standard engine testing specifications as approved by the FAA.

Engine Model R-TS10360EB1B

Engine Serial Number 1048107

Testing Completed

Standard Acceptance Test:

Date of Completion 26 OCT 24 Test Operator *Matthew Chittip*



Continental Motors, Inc.

Form No 98344



Continental Motors

Engine Component Information Sheet

Printed:12/13/2024

Serial:1048331

Spec:LTSI0360EB1B

New/Rebuilt:(REBUILT)

Assembled: / /

Shipped: / /

Packed: / /

DEC 13 2024

Customer Name:

Shipping Address:

Component	Serial Number
CAMSHAFT	552498-8
CRANKSHAFT	N24IF864
CRANKCASE	S12GA087
CONNROD	AE23HJ224CP
CONNROD	AE23HJ062CP
CONNROD	AE23HJ241CP
CONNROD	AE23HJ257CP
CONNROD	AE23HJ238CP
CONNROD	AE23HJ229CP
L MAGNETO	D24JD419
R MAGNETO	D24JD414
FUEL PUMP	B24HB431
MANIFOLD VALVE	C24IB497
METERING UNIT	A24HB129
STARTER	H-I-282407
ALTERNATOR	H-Y101326

Component	Serial Number
STARTER ADAPTER	H-Y021252
R. TURBO	H-TS1024006
OVERBOOST	H-BIO00011
OIL COOLER	H24-34818-86
CYLINDER-1	AC24KA824
CYLINDER - 2	AC24KA394
CYLINDER - 3	AC24KA835
CYLINDER - 4	AC24KA389
CYLINDER - 5	AC24KA837
CYLINDER - 6	AC24KA187
NOZZLE - 1	1229
NOZZLE - 2	2229
NOZZLE - 3	3229
NOZZLE - 4	4229
NOZZLE - 5	5229
NOZZLE - 6	6229



Pack Inspection Stamp

All of the information provided herein is subject to verification by the user. Continental Motors, Inc. makes no representation or warranty concerning the accuracy or completeness of the information and assumes no responsibility with respect thereto.

CONTINENTAL®
2039 SOUTH BROAD STREET
MOBILE, ALABAMA 36615

+251.438.3411
1.800.718.3411



RE: SO#SO15223 and SO13800
PO#POE5796 and POE5795
R-LTSIO-360-EB1B and R-TSIO-360-EB1B

Date: January 8, 2025

Dear Mr. Fino,

Continental agrees to honor a 27 month warranty on both subject engines. Continental has also agreed to full core credit, once the engine cores have been returned. This is part of a concession for issues experienced during your order process.

Sincerely,

Dana Durden
Continental Aerospace Technologies Customer Support

[illegible]